

# SALT

PRESSURE BAR	AP 22	AP 38-1	AP 38-2	AP 38-3	AP 38-4	AP38-5	AP 50-1	AP 50-2	AP 50-3	AP 50-4	AP 50-5	AP 75-1	AP 75-2	AP 75-3	AP 75-4	AP 75-5	AP 75-6	AP 75-7
	KGS PER MINUTE																	
6.5	4.8	6.4	10	15	20.9	34	6.3	9.2	13	18.3	20	5.6	7.4	10.5	16.7	23.5	43	66
6	4.2	6.1	9.6	14	20.1	32.7	4.8	7	10	14	15.9	4.8	6.5	9.2	14.5	20.4	37	58
5	3.6	5.4	8.4	12.6	17.6	28.6	4	5.9	8.4	11.8	13.4	4.1	5.5	7.8	12.4	17.4	31.6	49

# CORN

PRESSURE BAR	AP 22	AP 38-1	AP 38-2	AP 38-3	AP 38-4	AP38-5	AP 50-1	AP 50-2	AP 50-3	AP 50-4	AP 50-5	AP 75-1	AP 75-2	AP 75-3	AP 75-4	AP 75-5	AP 75-6	AP 75-7
	KGS PER MINUTE																	
6.5	7.1		23.8	35.7	49.8	81.2	21.1	30.8	43.7	61.6	69.7	40.5	54	76.5	121.5	171	310	481
6	6.7	14.3	22.5	33.7	46.9	76.6	20.2	29.5	41.9	59	66.8	38.2	50.9	71.7	114	161	290	450
5		13.1	20.5	30.7	42.7	69.7	18.6	27.2	38.6	54.4	61.6	34.7	46.3	64.6	103	146	260	409

# SUNFLOWER

PRESSURE BAR	AP 22	AP 38-1	AP 38-2	AP 38-3	AP 38-4	AP38-5	AP 50-1	AP 50-2	AP 50-3	AP 50-4	AP 50-5	AP 75-1	AP 75-2	AP 75-3	AP 75-4	AP 75-5	AP 75-6	AP 75-7
	KGS PER MINUTE																	
6.5	7	15.8	24.8	37	51.9	84	17.5	25.5	36.3	51	58	15.2	20.3	29	45	64	116	180
6	6.3	7	11	16.5	23	37	17	24.8	35.2	49.6	56	13.7	18.3	25.9	41	58	105	160
5	5.6	2.8	4.4	6.6	9.2	15	15.2	22.2	31.6	44.5	50	12.3	16.4	23.2	37	52	94	146

# WHEAT

PRESSURE BAR	AP 22	AP 38-1	AP 38-2	AP 38-3	AP 38-4	AP38-5	AP 50-1	AP 50-2	AP 50-3	AP 50-4	AP 50-5	AP 75-1	AP 75-2	AP 75-3	AP 75-4	AP 75-5	AP 75-6	AP 75-7
	KGS PER MINUTE																	
6.5	9.6	8.7	13.6	20.4	28.4	46.4	12.1	17.7	25.2	35.5	40.1	15.2	20.2	28.7	45.6	64.1	116	180
6	7.8	7.7	12.1	18.2	25.3	41.2	9.5	14	19.8	27.9	31.6	5.1	6.8	9.6	15.2	21.4	38.8	60.2
5	5.8	6.6	10.4	15.6	21.7	35.3	7	10.2	14.5	20.5	23.2	3.5	4.7	6.7	10.6	15	27.2	42.1